






REPLACEMENT SHEET

1/8



REPLACEMENT SHEET

2 / 8



3 / 8




FIG 6A








FIG 6B

REPLACEMENT SHEET

4 / 8



REPLACEMENT SHEET




FIG 9




FIG 10




FIG 11

IMPROVEMENTS TO A BLOOD COLLECTION DEVICE
DON CHANNER
SERIAL NO. 10/587,139
ATTORNEY DOCKET NO. CUL-0023
Cantor Colburn LLP, 20 Church Street, 22nd Floor, Hartford, CT 06103
REPLACEMENT SHEET




FIG 12




FIG 13




FIG 14

IMPROVEMENTS TO A BLOOD COLLECTION DEVICE
DON CHANNER
SERIAL NO. 10/587,139
ATTORNEY DOCKET NO. CUL-0023
Cantor Colburn LLP, 20 Church Street, 22nd Floor, Hartford, CT 06103
REPLACEMENT SHEET




FIG 15




FIG 16




FIG 17

REPLACEMENT SHEET

8/8




FIG 18